#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-022709 Address: 333 Burma Road **Date Inspected:** 05-Mar-2011

City: Oakland, CA 94607

OSM Arrival Time: 1500 **Project Name:** SAS Superstructure **OSM Departure Time:** 300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

## **Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Mike Hasler was present during the times noted above for observations and testing relative to the work being performed.

### Bay 3

This QA inspector performed a random observation for the OBG. During the observation performed it was noted ZPMC was in process of welding weld repair on Architectural Housing subassembly AH3150-002. ZPMC QC inspector Zhang Ya Xu was present at this time of this observation and informed this QA inspector of the work that is in process and identified Zhu Tian Shu as the CWI. It was stated that ZPMC had 1 welder and identified the welder by ZPMC welder identification number appointed to then by ZPMC. This QA inspector verified this information for the following location;

WR20318 Weld- AH3150-002 WPS-345-SMAW-1G(1F)-Repair Welder-058102 1G/CJP/FCAW

### Bay 11

This QA inspector performed a random observation for the OBG. During the observation performed it was noted that at Bay 11 ZPMC was in process of welding. ZPMC QC inspector Shao Hai Lang was present at this time of this observation and informed this QA inspector of the work that is in process and identified Zhao Chen Sun as the

# WELDING INSPECTION REPORT

(Continued Page 2 of 3)

CWI. It was stated that ZPMC had 3 welders and identified the welders by ZPMC welder identification number appointed to then by ZPMC. This QA inspector verified this information for the following location;

Weld-32TR2-016, 015, 012, 005, 004, 001 WPS-B-T-2231-ESAB Welder-053316, 040785 1G/FCAW/CJP

Weld-30TR2-001, 004, 005, 015, 012, 016 WPS-B-T-2231-ESAB Welder- 040785 1G/FCAW/CJP

## Bay 10

This QA inspector observed ZPMC in process of welding and heat straightening. ZPMC CWI Guo Yan Fei was present at this time of this observation and informed this QA inspector of the work that is in process. It was stated that ZPMC had 5 welders and identified the welders by ZPMC welder identification number appointed to then by ZPMC. This QA inspector verified this information for the following location;

Weld Repair Per ZPMC UT-20330 Weld- TR-039-009, 011, 013, 015, 017 WPS-345-SMAW-2G(2F)-Repair Welder- 500363, 040511, 052493, 057258 1G/SMAW/CJP

Weld-BK17C-001-031 WPS-B-T-2133-ESAB Welder-057266 3F/FCAW Cantilever Box

Heat Straightening HSR1 (B) 10129 BK009A

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## **Summary of Conversations:**

"As noted within the contents of this report."

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or 1500026784, who represents the Office of Structural Materials for remedial efforts please contact James Devey your project.

# **WELDING INSPECTION REPORT** ( Continued Page 3 of 3 )

Inspected By:	Hasler,Mike	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer